

Not to Scale

LEGEND

Seepage

__▽ Groundwater Table

NOTE

The thicknesses and elevations of these geologic units vary from place to place, and a unit could be missing due to previous erosion.

Seattle Landslide Study Seattle Public Utilities Seattle, Washington

IDEALIZED GEOLOGIC CONDITIONS WEST MAGNOLIA BLUFF

July 1999

W-7992-01

SHANNON & WILSON, INC. Geotechnical and Environmental Consultants

FIG. 3-2